

Daily Coordination Meeting



14:00 Sign In

Daily Coordination Meeting

General Topics:

- Winds this weekend



SW loading dock
ftg
5:00 am

SE loading dock
ftg
6:00 am


TB/25 landing
pad
6:30 am

SE loading dock ftg
6:00 am

TB/25 landing pad
6:30 am


SW loading dock ftg
5:00 am

UTILITY LEVEL PRESS T.





UTILITY LEVEL MOD1




BELFOR
Mold remediation

ELRAM
Drywall install

MEP+Electrical
Ready for re-install




UTILITY LEVEL MOD2







SUT 38.1 LEVEL




SUT 38.2 LEVEL




SUBFAB BUILDOUT MOD 1




SUBFAB CRC TOPCOAT




BCT Pressure Test Today



BCT Pressure Test Tomorrow



SUBFAB BUILDOUT MOD 2






SUBFAB BEAUTY COAT PAINT





SUBFAB BEAUTY COAT PAINT











| | | | East Side | | | | | | West Side | | | | | |
|------|----|------|-----------|--------|--------|--------|---------|--------|-----------|---------|---------|---------|---------|--------|
| Year | WW | Date | AC/11 | AC/13 | AC/15 | AC/18 | AC/20.5 | AC/22 | AG/11 | AE/13 | AG/15 | AE/18 | AG/20.5 | AE/22 |
| | | | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 |
| 7 | | | | | | | | | | | | | | |
| 2024 | 49 | 1 | 456940 | 444320 | 455680 | 424860 | 439520 | 416740 | 418180 | 418480 | 435320 | 441800 | 431320 | 407000 |
| | 49 | 2 | 537400 | 547420 | 690940 | 779540 | 715720 | 650840 | 1127860 | 1007140 | 1098880 | 1066100 | 835400 | 793540 |
| | 49 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| | 49 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

There was an increase with particles count over AE-AG gridlines. Observations at the interstitial has shown high levels at same locations. Need to make sure area is left clean and tidy by end of the day.






Siding - East FAB - PSSS


[illegible]


Siding - West FAB - JYG

[illegible]




Walk path






PSSS.1

Utility Level 1YA




PSSS Roof 2SA




PSSS.2

Utility Level 1YA




PSSS Roof 2SA





WJG 01J, 02J LIFT 2 & 3







WJG 03J, 04J, 05J LIFT 2 & 3



MAH101-9/10-00 Delivery WW49








CUB 1

CUB 1 COORDINATION MAP

UPDATED __ / __ / __




N

- PROTECTED AREA
- STAIRS / RAMPS
- YARDS
- TRUCK OFF/LOADING


ALARM NOTES:
1. FIRE ALARM: WAIT FOR HCC DIRECTION
2. GAS ALARM: EVACUATE TO NORTH YARD

BUILDING NOTES:
1. Fire Alarm System
Devices are actively monitored
Boiler room and Roof Charged with Water WW43
2.


CUB 1 – EXTERIOR/ROOF




CUB 2- INTERIOR/LOAD-IN



CUB 2 – EXTERIOR/ROOF







HOFFMAN CONSTRUCTION COMPANY



HOFFMAN
Sparrow



T18

DEC 3th - DEC 11th

DEC 8th


DEC 9th

DEC 10th

DEC 3th

DEC 3th


DEC 3th



Daily Coordination Meeting

Site Logistics


North



Daily Coordination Meeting

Site Logistics


East CUB1 Road Closure



Daily Coordination Meeting

Site Logistics

South



Slick Surfaces

- Reminder to ensure that you have the proper controls in place if working in an area with wet conditions.
- We have had a couple of slips recently due to the wet condition of the roofs.
- Make sure that boots are in good condition with non-slip soles if you will be working in these areas, or have a non-slip surface to work from.
- Stay on designated paths and report if conditions are not favorable to prevent a slip.
- Take your time and do not rush.

Daily Coordination Meeting



14:00 Sign In