



HOFF MAN Sparrow = =


Room Ready

BCR & SCR Operational Readiness Tracker

		•			CSA & MEP
	AND THE SECOND	Elram start	clean start	small wires start	
East	AC/AD	10-נוב	-17 נוב	20-נוב	
	SCR-LC211D AM/AN	-17 מב	-24	-01 דצמ	
	SCR-LC211F AU/AV	-24	-01 דצמ	-08 דצמ	
	SCR-LC211H BB/BC	-24	-01 דצמ	-08 דצמ	
	SCR-LC211K BJ/BK				
West	BCR-LC211A AC/AD				
	SCR-LC211C AM/AN	-17 נוב	-24	-01 דצמ	
	SCR-LC211E AU/AV	-24	-01 דצמ	-08 דצמ	
	SCR-LC211G BB/BC	-01 דצמ	-08 דצמ	-15 דצמ	
	SCR-LC211G BB/BC	-01 דצמ	-08 דצמ	דצמ-15	
		Task Obstructed or not Open			
		Task Possible/Open/Infrastructure Present			
	%	In Progress			
		Done			

BCR 1E BCR 1W

Starting to Close and change locks for cleaning beginning on 20th of November








HOFFMAN CONSTRUCTION COMPANY UTILITY LEVEL MOD1 Room Ready






















BELFOR Mold Remediation SCR 4E LSS 4E SCR 2W SCR 2E Turnover this week


ELRAM Drywall install

MEP+Elctrical (AFCON, Bynet, AfconCtrl, Megason, Chemo ahron..) Ready for re-install

WW RHS for roll-up doors













SUT 38.1 LEVEL







SUT 38.2 LEVEL




Vesda


Need to install

on the West.


SUBFAB BUILDOUT MOD 1




SUBFAB CRC TOPCOAT




BCT Pressure Test



SK IA Pressure Test




SUBFAB BUILDOUT MOD 2




































PL1&2 Protocol Training for Clean Zone Total of 613



Violations Control - Stop work





Trade Protocol Champions Program:


<u>Objective</u>: establish strong relationship with direct comunication with Trade workers and Management to achive high level of Protocol performance


Help needed:

- One or Two rep's from each Trade (requires company e-mail)
- · Avelabilty for Training and group formation
- Slot for protocol updates at the Trade tool box












PSSS.1



PSSS.2



500T Build for PSSS 11/11-12/11



TC3

Dismantle

13/11


14/11

(Nights)


650T Set up NOW




IA
Pressure
Test
13/11
17:0004:00















IA Pressure test Exclusion Zone 13/11/2024 Night Shift






WJG UTILITY LEVEL BUILD OUT








CUB 1- Start up logisitics












CUB 2- Load in and H&T

































Daily Coordination Meeting







Daily Coordination Meeting

Site Logistics

South





LEARN FROM EVERYTHING



ALL INJURIES ARE PREVENTABLE | PEOPLE ARE THE SOLUTION | SUCCESS IS THE PRESENCE OF SAFETY

DATE/TIME OF INCIDENT: 11/06/2024, 6:30 AM **LOCATION** Fab 52.2 Sub Fab CN-12

:

WHAT HAPPENED?

A 5' stick of 1" EMT conduit fell from the Sub Fab to the utility level through a floor opening. The conduit was being installed vertically and slipped from the employee's hand after they hit a strut cross bracing above the install location. The conduit fell straight down, hit their tool cart and kicked towards the floor opening and went through the mesh between the mid rail of the Unistrut guardrail system and the curb around the floor opening. The mesh was not secured at the bottom and folded up when the material hit it.

CURRENT SITUATION/CONTAINEMENT?

Floor opening is protected by guardrails and mesh.

ROOT CAUSE

Work Environment / Conditions of Work Area


WHAT CAN THE PROJECT LEARN FROM THIS INCIDENT?

Secure all material, verify effectiveness of protective measures.

WHAT CORRECTIVE ACTIONS ARE BEING TAKEN?

When working near a floor opening that is protected by a Unistrut guardrail system and mesh snow fence that is not secured at the bottom, a hard barrier or a piece of strut is to be added to the bottom of the mesh to keep it weighed down to secure material coming from the side. Barricade lower levels if there is a potential for material to drop there.







LEARN FROM EVERYTHING



ALL INJURIES ARE PREVENTABLE | PEOPLE ARE THE SOLUTION | SUCCESS IS THE PRESENCE OF SAFETY

DATE/TIME OF INCIDENT: 10/22/2024 8:40 PM **LOCATION** Fab 52.1 Subfab BD 10

WHAT HAPPENED?

Employee was moving around in the racks placing clamps on a 1 ½" pipe. When the employee reached down to lift the pipe into place to apply the clamp, they felt a pop in their back. The employee did not feel pain and continued to work. The following morning when the employee woke up, they began to feel throbbing pain in their lower back.

CURRENT SITUATION/CONTAINEMENT?

The employee is currently work to tolerance. There was no damage to the facility.

ROOT CAUSE

Work Environment / Confined Work Area


WHAT CAN THE PROJECT LEARN FROM THIS INCIDENT?

Support employees on recognizing hold points. Remember to stop work, pause, and re-evaluate location on work plan. Crews to be encouraged to use their stop work authority. Crews to engage with their Foreman and Safety to create a plan that incorporates ergonomics in congested work areas.

WHAT CORRECTIVE ACTIONS ARE BEING TAKEN?

- Conduct Toolbox Talk on the following:
 - Ergonomics
 - Incident/Injury Reporting
 - Document Retention
- Audit to confirm Foreman have completed the Risk Tolerance training to allow them to better evaluate areas.





HCC/EHS Weekend Work- 08.11.2024

White Board Meeting in Beavers at 06:30

Superintendents

Carter Miles 052-3376046 David Kanzevich 052-2045446

Nisim Asis 052-5762515

CSA CM

Idan Dahan 052-5949702

MEP

Paschalis Papadopoulos 052-2168215

Sean Ghee 052-6637316

Tony Dixon 052-3952068

Yaruslav Zemskich 052-2438340

Simon Garton 052-2770953

Sean Murphy 052-2563950

OSM

CX/QA

Cranes

Yossi Atias 052-3060790

Safety

- Safety Foreman- Adir Elmakayes- 054-7254767 <u>Adir-Elmakayes@Hoffmancorp.com</u>
- Safety Assistant- Hudifa Alshieck- 054-9408858 <u>Hudifa-Elscheich@Hoffmancorp.com</u>
- Safety Professional Anan Ragbe- 058-7708886 <u>Anan-Rajbi@Hoffmancorp.com</u>

Subcontractor Weekend Work- 08.11.2024

FAB

Utility Level / Roof / Stair Shaft

Lesico

Ehs Michel 0526060223 Foreman Manoj 0522450258

Combe UPW

Ehs: Michael 0525506596 Foreman; Edward 0526419894

Elram

Foreman: Shlomo 0545551702

Ehs: shy 0523632132

Afcon electrical

Ehs Steven 0559129333 Foreman Perdit 0552742935

SK

Ehs Om 0542072285 Foreman Shy 0545654760

Subfab

Pach Taas

1w & 1e mars Edi: 0547915874

Afcon E

Mars 1W + LSS rooms

Team Lead: Avi Eli 0526008487

Belfor

4w & 5w Lss rooms Salame: 0546651886

Chemo

TTNW RSTM

Tommy: 0523759408

Clean Room

Talad – CR 1W – Graidings Install, 4E Grating Marcelo 0523540242 , Super Igor 0544509386)

Sig – 5W INT 4W, 3E Handrails (EHS Beni 0506232032, Super Nodar 0546313261)

Elram – CR Level 9,25 line columns, upper shaft wall, TB-TC/25 Columns (EHS Royi 0538312234, Super Bonio 0544236899)

Afcon – CR – 2E boxes 5W supports, 2W modules (EHS Lokanath – 0559652398, Supervisor Pradeep - 0552742935)

Rolling Plains – INT NTT 5RA, Marshaft 3E, 5RA, MOD2 CA CD17,24,10 (Super Cordin 0546594273, EHS Ovidiu 0546993648)

Chemo – INT -TNTNE/W Supports, 1E Mars prep for PT , 1W Mars (EHS Lila - 0547886704, Supervisor Winai – 0528090588)

Talent – CR Level 1E/2E – Superclean (Supervisor/EHS – Hasan 0542662054)

Sela – 17-25 Line CRC (Supervisor Yoav 0548076339, EHS Shmuel – 0506306031)

Subcontractor Weekend Work- 08.11.2024

PSSS

Pach Taas – Module bolting PSSS Roof, Lift 2 1-3P Foreman – Vadim – 053-5552472

Safety - Offek - 050-2161429

Afcon Electrical – Cable Tray and Cable Pulling 1-5P UL and 1-3P Roof & Lift 2

Foreman – Charles – 055-2740190

Safety - Stevan - 055-9129333

Chemo A. – PSSS Roof and Lift 2 1-5P

Foreman – Maor – 050-955-9071

Safety – Rotem – 054-447-7112

W&W – SEQ 135, 138 (lift 3 3P)

Foreman - Willie - 052-6145521

Safety - Gary Lambert - 1-405-833-8910

Elram – 1P and 2P Exit Passage Ceiling

Foreman – ???

Safety – ???

Combe UPW - UPW Room Piping and Yard

Foreman – Boris – 054-8346412

Safety - Shimon - 054-5348843

Lesico - Roof Rack 2P

Foreman – Saju Paily – 052-7755967

Safety - Shilat - 050-05891373

SK Engineering – GL4 Rack UL, Lift 2 2P Piping

Foreman – Marcela – 054-5210133

Safety – Marzuke – 054-447-7112

WJG

W&W – Steel Erection 5J lift 2 Erection / Detail Work

Foreman: Chris Isaac 052 588 3215

Safety: Moshe 054 801 2959

Afcon – 2J Lift 3 Cable Pulling
Foreman: Montu 055 911 6973

Safety: Pradeep 055 274 2935

Chemo: 5J Lift 2 Piping

Foreman: Sergey 054 465 9688 Safety: Rotem 054 447 7112

<u>Siding</u>

SN

Victor- 0549220163 Ranpero- Roofing Omar 0525959621

Subcontractor Weekend Work- 08.11.2024

<u>CUB</u>

Sela south yard:

Yoav - 0548076339

Shmuel - 0506306031

Sami Najami CUB 1+2:

Faiz - 0502227962

Husein - 0526917461

Alon - 0509895008

SK CUB 1+2:

Mario - 0548991051

Renato - 0548991623

Meptagon I+C CUB 1:

Sergey - 0537981592

Yuval - 0533346481

Chemo Aharon CUB 1:

Dudu - 0509808846

Leonid - 0548883878

Trestle

SNJ:

PIPES – 10 workers UB CUB+ T30 FORMAN

ATEF- 0542287499 SAFETY TRESTLE

BARAK MESIKA tel-0542262530

GIS/NEY

Site

Derech Afar – Shotcrete wall Supervision = Raed: 054-244203

EHS = Alex: 054-5403849

Olizki – Sweepers and water trucks, backfill CUB2 south, GUT road grading

Supervision = Or: 052-4917313

EHS = Ben: 052-4033565

