

Daily Coordination Meeting



14:00 Sign In

Daily Coordination Meeting

General Topics:

- Power in Fab this week- 33kv
- Buggy stickers (see QR code)



Responsible Person's Name *

Orange Badge Number *

ID *

Company *

Phone Number *

Does the buggy have a buggy whip/flag? *

This is required to be on the buggy. Submit photo below.

Does the buggy have a company sign on it? *

This is required to be on the buggy. Submit photo below.

Does the buggy have a shakalaka (amber strobe) light? *

This is required to be on the buggy. Submit photo below.

Email Address- Must Be a Company Email *

The email cannot be a gmail, yahoo mail, or anything other public email. It must be a company email.

License Plate Number *

Comments from Requester

Upload Picture of Buggy- Including the whip, sign, and strobing light *

Picture should show all 3 elements.



Daily Coordination Meeting

Cub 2 zone 5 SOMD @ 12:00 am

PSSS samp @ 12:00 am

South elevator precast slab(2)
@ 12:00 am

CUB roof zone 5
SOMD 12:00 am

PSSS samp
@ 12:00 am

Precast slab(2)
@ 12:00


FAB-28

HAPPY BIRTHDAY BRO, WE LOVE YOU!







UTILITY LEVEL MOD2



UTILITY LEVEL MOD1




UTILITY LEVEL MOD2






SUT 38.1 LEVEL





SUT 38.2 LEVEL



Rack 7(1A West)


1A Rack
Lifting

8 Rack


SKE
H&T
CRW
Move-In date ?

Vesda
H&T

SUBFAB BUILDOUT MOD 1



SUBFAB BUILDOUT MOD 2




**1W South
Starts Aug 11**


CRC Beauty Cote Work Plan.


Be well prepared to protect CRC


1. Nothing touches the floor, All must be on wheels.
2. Carts & MEWPs wheels must be replaced with a cleaner type (White).
3. Always have protective sheets/board on site to use for cover areas.
4. Damaging CRC will cause unnecessary and painful expenses to your company.


**1W North
Starts Aug 4**



















PSSS.1


Utility Level 1YA

PSSS Roof 2SA



PSSS Roof 2SA







WJG 01J, 02J LIFT 2 & 3





WJG 03J, 04J, 05J LIFT 2 & 3





WJG UTILITY LEVEL BUILD OUT

















Bynet - AIS
- Term FO cables

SIEMENS / Pach Taas
AIS - Exhaust fans instal

NO ENTRY
HV ENERGIZED AREA

TMT
- Z 8-FP line inspection & wrapping
- Z 8 liftstation sear works
- Z 5- sealing drainage manholes


Elmor-
AIS-pull control cables
SES- Rd valve term

TMT-Rimon Intel
DW-vac truck UGU



HOFFMAN CONSTRUCTION COMPANY





HOFFMAN CONSTRUCTION COMPANY




HOFFMAN
Sparrow  

T-17

Trestle - MOD 2 Steel erection

6-7 August



BSGS




NDT radiography test at BGC vacuum tanks area


Spoter

Spoter

**Wednesday night July 31st at
22:00
Finish on August 1st at 05:00am**


FAB GIS PERMENENT POWER
AUGUST 8TH 4PM.





Daily Coordination Meeting

Site Logistics
North Gate B






Daily Coordination Meeting

Site Logistics


Traffic Plan



Daily Coordination Meeting

Site Logistics


North



Daily Coordination Meeting

Site Logistics

South





HOFFMAN CONSTRUCTION COMPANY




Daily Coordination Meeting

Site Logistics

SW Parking


Sanitary



Daily Coordination Meeting

WATER BOTTLE FILLING & PERSONNEL COOLING STATIONS


BF (1) AT GIS



Open CORs by Subcontractor

WW 31 – 436 CORs


WW 32 – 440 CORs



Overdue CORs by Subcontractor

WW 31 – 132 Overdue CORs

WW 32 – 169 Overdue CORs



Pattern Interrupts This Week

- The topic is back to basics.
- Pattern interrupts are in field stand downs with smaller groups of people.
- These are not optional for persons working on site. We will be taking attendance.
- We have had a worrying trend of incidents on the project and need everyone here to stay engaged and help get the teams on the right track.



Heat Index– August 1st

	temperature (°F)																
	80	82	84	86	88	90	92	94	96	98	100	102	104	106	108	110	
Relative Humidity (%)	40	80	81	83	85	88	91		97	101	105	109	114	119	124	130	136
	45	80	82	84	87	89	93	96	100	104	109	114	119	124	130	137	
	50	81	83	85	88	91	95	99	103	108	113	118	124	131	137		
	55	81	84	86	89	93	97	101	106	112	117	124	130	137			
	60	82	84	88	91	95	100	105	110	116	123	129	137				
	65	82	85	89	93	98	103	108	114	121	128	136					
	70	83	86	90	95	100	105	112	119	126	134						
	75	84	88	92	97	103	109	116	124	132							
	80	84	89	94	100	106	113	121	129								
	85	85	90	96	102	110	117	126	135								
	90	86	91	98	105	113	122	131									
95	86	93	100	108	117	127											
100	87	95	103	112	121	132											

 Caution

 Extreme Caution

 Danger

 Extreme Danger

Extreme Caution

- Ensuring water and shaded areas available
- Acclimating workers
- Emergency planning and response
- Training workers and supervisors on the signs of heat stress and preventative measures
- Modified work schedules and/or rotating out workers
- Monitoring of workers for signs of heat stress

Daily Coordination Meeting



14:00 Sign In