

# Daily Coordination Meeting




14:00 Sign In

# Daily Coordination Meeting

## General Topics:

- **Don't Let Complacency Be a Reason for Communication Breakdown**




SWTT 4DA - AHU  
2:00 am

WSUT2 curb  
3:00 am

RWS-20 SOMD  
10:00 pm




# UTILITY LEVEL MOD2



Utility Level MOD2  
Don't bring any material without coordination with Oscar M.  
Staging material is possible but must be coordinated and must follow the rules (no combustibles, nothing touch the floor ETC.)  
Thanks.


SUT 38.1 LEVEL

OH roll-up door  
Install  
?



HYG  
SOG platform install  
Ongoing

# West SUT2 Rack 6



16/02/2025	Module 1
20/02/2025	Module 2
23/02/2025	Module 3
26/02/2025	Module 4
02/03/2025	Module 5
04/03/2025	Module 6


SUT 38.2 LEVEL

Rack 1B  
Pending  
lifting EQP


Rack 4b  
Inter  
Connection's

Rack 6  
MIMO -  
Module #1  
16.2.25


Rack 2  
MIMO -  
Module #12  
10.2.25



# SUBFAB BUILDOUT MOD 1




# SUBFAB CRC TOPCOAT







# BCT Pressure Tests Tomorrow









**Afcon** - Cable trays, modules and stickers  
**MB**- Fire sprinklers  
**Elram** - Columns/G1 wall  
**Chemo**- Skids and pipes  
**SK**- IA pipes  
**Tzur-esh** - Paint+ touch ups  
**WW** - Cat walk  
**RPC** - 4DA/5DA FP  
**Tavas** - Super clean  
**Bynet**- Communication weirs  
**Megasone** - Speakers

**NETT**  
**MB- FS** install touch ups  
**Chemo**- Racks onging  
**Megasone** - Small wires+Speakers  
**AFA**- Vesda  
**NWTT**  
**Chemo**- Racks  
**MB- FS** install

**Chemo**-  
**1W-2E** flushing ongoing

**JUNGLE GYM**

**INTERSTITIAL**

**30%**

**60%**

**1E**

**2E**

**3E**

**4E**

**5E**

**1W**

**2W**


**3W**

**4W**

**5W**

TA TB TC AA AB AC AD AE AF AG AH AJ AK AL AM AN AP AQ AR AS AT AU AV AW AX AY AZ BA BB BC BD BE BF BG BH BJ BK BL CA


01  
02  
03  
04  
05  
06  
07  
08  
09  
10  
11.3  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21.3  
22  
23  
24  
25  
26  
27  
28





**Alimak Shut Down**  
night Shift  
Sunday + Monday  
from 16:00 p.m till  
05:00 a.m





Up coming	
Girtz	
Siding	
Seq done	
material lay down	

E-House

E-House

Trestle

Walk path

Walk path

4.5 line  
Sut-E

BJ

BG

BC

AZ

AV

AS

AP


AK

AU

AC

AA

17




Up coming 

Girtz 

Siding 

Seq done 

material lay down 

1011C  
1012C

TA  
TB  
TC

902C/  
901C

911A  
912A

911C  
912C


9

13

17

23


25



# PSSS.1

## Utility Level 1YA

## PSSS Roof 2SA



# PSSS.2

**6P**


**7P**

**8P**


**9P**

**10P**

Utility Level  
1YA




PSSS Roof  
2SA






GUT ROAD  
CLOSURE  
10/02 @  
14:00-18:00





# WJG 01J, 02J LIFT 2 & 3




# WJG 03J, 04J, 05J LIFT 2 & 3







# CUB 1




# CUB 1 Exterior Pre-Punch Status



1. UN2 Lesico piping complete needed to close penetrations
2. SWS Make up and Temp shower water lines need to be removed from Building openings
3. Boiler room wall repairs Feb 9-19



# CUB 1 – EXTERIOR/ROOF




# CUB 2- Load in ,H&T, Framing and Sheetrock

## CUB 2 COORDINATION MAP



A B C E F G H J K L M N P Q R S




NORTH YARD

SOUTH YARD

MIMO

# CUB 2 – EXTERIOR/ROOF





# Daily Coordination Meeting

Site Logistics

North Entry



# Daily Coordination Meeting

Site Logistics  
North



# Daily Coordination Meeting

Site Logistics

South



# Spotters & Operators

- Operators are responsible for the safe operation of their equipment/vehicle.
- When there is a spotter used to assist them with navigating through areas, they are also responsible for that person.
- This means, before they move their vehicle or equipment they need to verify the location of their spotter, make sure they are out of the moving path of the vehicle, and they need to communicate where they are moving.
- It can be deadly to not know where the spotter is, as they could be struck by the vehicle. Yes, spotters should not stand in the line of fire, but the added layer of defense here is for the operator to not move until they know exactly where their spotter is.
- This also allows the spotter to make sure that the operator can/should be moving in the planned direction.

# Daily Coordination Meeting



14:00 Sign In